



ಬೃಹತ್ ಬೆಂಗಳೂರು ನಗರಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	2	Chowdeshwari Ward
Street ID	Street Name	Significant Landmark
W0336, W0346	R H B Colony, 6th Crs, NA	Western Side and Eastern Side of Kamakshamma
Segment No.	Total Length (m)	
2/S-W0336/S104825	163.35	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.62	77.591747	13.106081	77.592283	13.106013	W0385	DEAD END
2	104.73	77.591370	13.106402	77.592330	13.106300	W0385	W0399

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC Drain at 1st and 2nd Cross Roads Western Side and Eastern Side of Kamakshamma in Ward no 02 of Yelahanka Sub-Division Yelahanka zo	1950000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	Work Details	Job No. / Work Code
Tender	Construction of RCC Drain at 1st and 2nd Cross Roads Western Side and Eastern Side of Kamakshamma in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000007
Work Order No.	Work Order Date	Period of Extention
EE (Y.N.K.D)E-PMT-1/WO/18/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked / Released (Rs)
G VENKATEGOWDA		0.00
Phone No.	E-Mail ID	

Zone: YELAHANKA Ward No: 2 Ward Name: Chowdeshwari Ward Street ID: W0336, W0346

Date: 06/12/2016 Time: 23:02:55 RH 20161206230255 Page 1 of 3

Engineer
Yelahanka Sub-Division
BBMP Yel. ZD

Field Inspection Details

Name

DAYANANDA

Number of Trees

5

Any Other Information

Date of Inspection

06/12/2016

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 2

Ward Name: Chowdeshwari Ward

Street ID: W0336,
W0346

Date: 06/12/2016

Time: 23:02:55

RH20161206230255

Page 2 of 3

[Signature]
 Executive Engineer
 Yelahanka Sub. Division
 Bangalore Urban Dist. (Zn)
 Bangalore

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	06/12/2016	05/01/2017	COMPLETED
SE	VASU K M	06/12/2016	05/01/2017	COMPLETED
EE	VASU K M	06/12/2016	05/01/2017	COMPLETED
AEE	DEVARAJ	06/12/2016	05/01/2017	COMPLETED
AE	DAYANANDA	06/12/2016	05/01/2017	COMPLETED
AE	DAYANANDA	06/12/2016	05/01/2017	COMPLETED


 Assistant Engineer
 Yelahanka S. B. Division
 (B&M P. Unit, 2nd)
 Yelahanka, Bangalore

Zone: YELAHANKA

Ward No: 2

Ward Name: Chowdeshwari Ward

Street ID: W0336,
W0346

Date: 06/12/2016

Time: 23:02:55

RH20161206230255

Page 3 of 3